

L Number	Hits	Search Text	DB	Time stamp
-	2200	(403/1,335-337,365,369,371,374.3).CCLS.	USPAT; US-PGPUB	2004/04/19 13:28
-	198	(403/1).CCLS.	USPAT; US-PGPUB	2004/04/19 13:50
-	18	((403/1).CCLS.) and bushing\$1	USPAT; US-PGPUB	2004/04/19 13:55
-	13	((403/1).CCLS.) and bushing\$1 not ((ball roller)adj bearing\$1)	USPAT; US-PGPUB	2004/04/19 15:36
-	0	((403/1).CCLS.) and bushings not ((ball roller)adj bearing\$1)	USPAT; US-PGPUB	2004/04/19 13:58
-	2	((403/1).CCLS.) and bushings	USPAT; US-PGPUB	2004/04/19 14:00
-	9730	shaft same bushings	USPAT; US-PGPUB	2004/04/19 14:00
-	851	shaft same flange same bushings	USPAT; US-PGPUB	2004/04/19 14:00
-	589	shaft same flange same bushings and axial\$2	USPAT; US-PGPUB	2004/04/19 15:03
-	409	shaft same flange same bushings not (ball roller)	USPAT; US-PGPUB	2004/04/19 15:03
-	4	((403/1).CCLS.) and bushing\$1 not (ball roller)	USPAT; US-PGPUB	2004/04/19 15:39
-	323	(403/369).CCLS.	USPAT; US-PGPUB	2004/04/19 15:39
-	7	("1805692"   "2514227"   "2755093"   "3298481"   "3405790"   "3667250"   "4041729").PN.	USPAT	2004/04/19 16:17
-	13	4311224.URPN.	USPAT	2004/04/19 16:18
-	390	(192/\$).ccls. and shaft and bushings	USPAT; US-PGPUB	2004/04/19 16:23
-	155	(192/\$).ccls. and shaft with bushings	USPAT; US-PGPUB	2004/04/19 16:24
-	315	(464/\$).ccls. and bushings	USPAT; US-PGPUB	2004/04/19 17:58
-	90	(464/\$).ccls. and bushings with shaft	USPAT; US-PGPUB	2004/04/19 18:12
-	11	("0912488"   "1672582"   "2038896"   "2124965"   "2125270"   "2307556"   "2641116"   "3103004"   "3866728"   "4028909"   "4572342").PN.	USPAT	2004/04/19 18:10
-	156	(464/41).CCLS.	USPAT; US-PGPUB	2004/04/19 18:14
-	646	bronze adj bushing	USPAT; US-PGPUB	2004/04/19 18:14
-	457	bronze adj bushing and shaft	USPAT; US-PGPUB	2004/04/19 18:14
-	271	bronze adj bushings and shaft	USPAT; US-PGPUB	2004/04/19 18:22
-	27	bronze adj bushings and shaft and bronze with (better benefit\$3 improv\$3 increass\$3 decreas\$3 friction)	USPAT; US-PGPUB	2004/04/19 18:22

	41	(US-4960192-\$ or US-4854434-\$ or US-4811824-\$ or US-RE34822-\$ or US-4928804-\$ or US-4438836-\$ or US-4378868-\$ or US-6364438-\$ or US-6213471-\$ or US-6186511-\$ or US-6176797-\$ or US-4944379-\$ or US-3622164-\$ or US-3793849-\$ or US-3798924-\$ or US-4036075-\$ or US-4036468-\$ or US-4304502-\$ or US-4809993-\$ or US-5297940-\$ or US-6375196-\$ or US-4317596-\$ or US-4311224-\$ or US-3957381-\$ or US-2816452-\$ or US-2508039-\$).did. or (US-4041729-\$ or US-2755093-\$ or US-5961247-\$ or US-4861201-\$ or US-4668206-\$ or US-4548305-\$ or US-6682430-\$ or US-5328009-\$ or US-5261517-\$ or US-4425813-\$ or US-3884049-\$ or US-6257985-\$ or US-4858791-\$).did. or (US-20030058531-\$ or US-20020160888-\$).did.	USPAT; US-PGPUB	2004/04/19 18:29
	7	((US-4960192-\$ or US-4854434-\$ or US-4811824-\$ or US-RE34822-\$ or US-4928804-\$ or US-4438836-\$ or US-4378868-\$ or US-6364438-\$ or US-6213471-\$ or US-6186511-\$ or US-6176797-\$ or US-4944379-\$ or US-3622164-\$ or US-3793849-\$ or US-3798924-\$ or US-4036075-\$ or US-4036468-\$ or US-4304502-\$ or US-4809993-\$ or US-5297940-\$ or US-6375196-\$ or US-4317596-\$ or US-4311224-\$ or US-3957381-\$ or US-2816452-\$ or US-2508039-\$).did. or (US-4041729-\$ or US-2755093-\$ or US-5961247-\$ or US-4861201-\$ or US-4668206-\$ or US-4548305-\$ or US-6682430-\$ or US-5328009-\$ or US-5261517-\$ or US-4425813-\$ or US-3884049-\$ or US-6257985-\$ or US-4858791-\$).did. or (US-20030058531-\$ or US-20020160888-\$).did.) and bronze "4944379"	USPAT; US-PGPUB	2004/04/19 19:05
	2	((US-4960192-\$ or US-4854434-\$ or US-4811824-\$ or US-RE34822-\$ or US-4928804-\$ or US-4438836-\$ or US-4378868-\$ or US-6364438-\$ or US-6213471-\$ or US-6186511-\$ or US-6176797-\$ or US-4944379-\$ or US-3622164-\$ or US-3793849-\$ or US-3798924-\$ or US-4036075-\$ or US-4036468-\$ or US-4304502-\$ or US-4809993-\$ or US-5297940-\$ or US-6375196-\$ or US-4317596-\$ or US-4311224-\$ or US-3957381-\$ or US-2816452-\$ or US-2508039-\$).did. or (US-4041729-\$ or US-2755093-\$ or US-5961247-\$ or US-4861201-\$ or US-4668206-\$ or US-4548305-\$ or US-6682430-\$ or US-5328009-\$ or US-5261517-\$ or US-4425813-\$ or US-3884049-\$ or US-6257985-\$ or US-4858791-\$).did. or (US-20030058531-\$ or US-20020160888-\$).did.) and (oil lubricant lubrication) same bushing	USPAT; US-PGPUB USPAT; US-PGPUB	2004/04/19 18:49 2004/04/19 19:06

-	2	((US-4960192-\$ or US-4854434-\$ or US-4811824-\$ or US-RE34822-\$ or US-4928804-\$ or US-4438836-\$ or US-4378868-\$ or US-6364438-\$ or US-6213471-\$ or US-6186511-\$ or US-6176797-\$ or US-4944379-\$ or US-3622164-\$ or US-3793849-\$ or US-3798924-\$ or US-4036075-\$ or US-4036468-\$ or US-4304502-\$ or US-4809993-\$ or US-5297940-\$ or US-6375196-\$ or US-4317596-\$ or US-4311224-\$ or US-3957381-\$ or US-2816452-\$ or US-2508039-\$).did. or (US-4041729-\$ or US-2755093-\$ or US-5961247-\$ or US-4861201-\$ or US-4668206-\$ or US-4548305-\$ or US-6682430-\$ or US-5328009-\$ or US-5261517-\$ or US-4425813-\$ or US-3884049-\$ or US-6257985-\$ or US-4858791-\$).did. or (US-20030058531-\$ or US-20020160888-\$).did.) and (oil lubricant lubrication) same bushing\$1	USPAT; US-PGPUB	2004/04/19 19:06
---	---	---	--------------------	---------------------